



BOMA Georgia

MEMBER

Structural Inspection and Safety for Building Operations



Agenda

- **Building Structure Condition Assessment**

- Scott L. Weiland PE SE, Innovative Engineering Inc.

- **Parking Deck Awareness**

- Mark E. Lester PE, Penta Engineering Group, LLC

- **Parking Deck Walk-Through**

- Mark E. Lester PE, Penta Engineering Group, LLC

Building Structure Condition Assessment

How to Avoid Catastrophe

BOMA BTO Safety Seminar
Thursday, August 11, 2022, 8:30-11:30 PM
Atlanta, GA

Learning Objectives

- **Building Structure Condition Assessment**

- Champlain Towers Collapse
- Structural Engineering 101
- Failure Mechanisms
 - Concrete, Masonry, Steel, & Wood
- Laws & Standards

AIA
Continuing
Education
Provider

Disclaimer

**Presentations today provide general information.
For specific advice, consult a professional.**

Innovative Engineering, Inc.



- **Scott L. Weiland PE SE**
 - **B SCE University of Michigan**
 - **Graduate Studies:**
 - San Jose State University
 - Georgia Institute of Technology
 - **Level I sUAS Thermographer**
 - **BESI Building Envelope Certified Level 2**
 - **Haag Certified Inspector – Commercial Roofs**
 - **Author, Presenter, Educator**




Champlain Towers Collapse


- Built 1981
- 12 Story, 136 Units
- Cast-In-Place Concrete
- Plaza Slab
- Below Grade Level Parking Garage
- 2018 Report
- 40 Year Recertification Underway



Plaza Slabs – Protected Membranes




Ref.: 1981 Architectural Graphics
Standards



Ref.: NRCA Detail WP-24

Building Structure - Definitions



Credit: James Burke

- **Foundations**
- **Columns**
- **Beams**
- **Slabs**


Building Structure - Columns

- **Failure Modes**



- Stress
 - Pure Compression
 - Combined Stresses
 - Shear
 - Lack of Confinement
 - Torsion
- Buckling



Building Structure – Beams and Slabs




Building Structure – Progressive Collapse




ASI Extreme Loading

Building Science – Sources of Deterioration


- Water Damage
 - Mold
 - Corrosion
 - Rot
 - Termites & Insects
- Movement of Materials
 - Thermal
 - Moisture
 - Elastic Deformation
 - Creep
- Other
 - Impact Damage
 - Lightning Strike
 - Overload
 - Wind, Earthquake, Flood




Deferred Maintenance Cost Curve




Deferred Maintenance Cost Curve



Deferred Maintenance Cost Curve



Deferred Maintenance Cost Curve




Reinforced Concrete

- Moisture
 - Corrosion
 - Freeze-Thaw
 - Sub-Efflorescence
- Cracking




Reinforced Concrete - Strength

Compression




10 % of Compression

Tension




Add Reinforcing


Tension




Reinforced Concrete – Simple Span Beam



Plain Concrete




Reinforced Concrete



Prestressed Concrete



Reinforced Concrete – Multi-Span Beam/Slab



- Tension
 - Top over Columns
 - Bottom between Columns

Foundation

Reinforced Concrete - Corrosion



- A: Spall
- B: Crack
- C: Corner Spall
- D: Delamination

Reinforced Concrete - Spall & Delamination



Spall



Delamination




Section Loss

Reinforced Concrete - Sounding





Sounding Technology Inc.


Reinforced Concrete – Impulse Echo



Champlain Towers Collapse – Punching Shear



Reinforced Concrete - Cracks



.013" \leq Cracks < .035"



Cracks that Leak < .035"

Reinforced Concrete – Crack Repair (Route & Seal)



Crack Chasing



Crack Sealant

Reinforced Concrete – Crack Repair (Epoxy Injection)



Cracks \geq .035"



Inflatable Injection Port


Photos by Engineered Restorations Inc.

Masonry

- Thermal Expansion/Contraction
- Moisture
 - Expansion/Contraction
 - Corrosion
 - Freeze-Thaw
 - Subefflorescence
- Cracking



Facade - Thermal Expansion




Coefficients of Thermal Expansion	
Material	in./in./°F x 10 ⁻⁶
Wood	
Pine (parallel to grain)	3.0
Pine (perpendicular to grain)	19.0
Masonry	
Brick	3.6
Limestone	4.4
Granite	4.7
Concrete Masonry Unit (CMU)	5.2
Marble	7.3
Concrete	
Concrete (Normal Weight)	5.5
Metals	
Steel	6.5
Copper	9.3
Aluminum	12.8
Finishes	
Glass	5.0
Gypsum Plaster, Sand	7.0
Gypsum Board	9.0

Façade – Thermal Expansion





No Expansion Joints




Creates Hinge at Corner

Facade - Moisture Expansion/Shrinkage



Façade – Moisture/Thermal Expansion/Contraction



Façade – Moisture & Thermal Expansion/Contraction




Façade – Corrosion Expansion



Façade – Moisture Damage



Masonry – Creep & Settlement



Masonry – Unauthorized Openings



- Penetrations:
 - Through Load Bearing Walls

Steel Framing - Deterioration

- Moisture
 - Rust
- Fatigue
- Modified or Damaged Members



Steel Framing Corrosion

- Surface Rust
- Section Loss
 - Flange
 - Web



Steel Framing - Corrosion

- Rust Expands:
 - 5 to 6 Times Original Volume
- Often Looks Worse Than It Is
- Scrape Rust
- Measure with Caliper



Steel Framing - Fatigue



Steel Framing – Altered or Damaged Members



Wood Framing - Deterioration

- Moisture
 - Rot
 - Insect Infestation
- Checks & Splits
- Missing or Modified Members



Wood Framing – Moisture Meter



Moisture Content > 30% =
Serious Decay

Wood Framing – Termite Infestation



Mud Tubes




Wood Framing – Termite Infestation

- Galleries
- Parallel to Growth Rings
- May not be visible
 - Thick lumber
 - Pressure Treated lumber



Wood Framing – Termite Infestation Probability



Note: Lines defining areas are approximate only. Local conditions may be more or less severe than indicated by the region classification.

FIGURE R301.2(6)
TERMITE INFESTATION PROBABILITY MAP
2000 INTERNATIONAL RESIDENTIAL CODE™

- Exist in all states except Alaska
- Live in a Colony (nest) in the Ground below the Frost Line
- Dark, Damp Environment
- Soldiers are ¼” Long and Whitish Crème in Color
- Can Penetrate 1/32” Openings.
- Travel in Shelter (Mud) Tubes to Shelter from Light

Wood Framing – Modified Members



Image: Russ LaBlanc



Structural Condition Assessment - Why

- Legal
- Deterioration
- Transfer of Ownership
- Change of Occupancy
- Renovation, Rehabilitation, and Restoration
- Strengthening or Hardening
- Damage
- Signs of Distress



International Property Maintenance Code (IPMC)


SECTION 304 EXTERIOR STRUCTURE

304.1 General. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare.

SECTION 305 INTERIOR STRUCTURE

305.1 General. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. *Occupants* shall keep that part of the structure which they occupy or control in a clean and sanitary condition. Every *owner* of a structure containing a *rooming house, housekeeping units, a hotel, a dormitory, two or more dwelling units* or two or more nonresidential occupancies, shall maintain, in a clean and sanitary condition, the shared or public areas of the structure and *exterior property*.

It's the Law!




ASCE Standard SEI/ASCE 11-99



- **Assessment**
 - Preliminary
 - Detailed
- **Materials**
 - Concrete
 - Masonry
 - Metals
 - Wood
- **Procedures**
- **Reporting**

CASE Contract #16 – Structural Condition Assessment



- **Document Review**
- **Visual Inspection**
 - Gravity Load path
 - Lateral Load path
- **Roof & Below Grade for Water Infiltration**
- **Façade Inspection**
- **Report**

Inspection Checklist



- **Sitework**
- **Safety**
- **Foundations**
- **Basement**
- **Superstructures**
- **Exterior Closure**
- **Roofing**
- **Partitions & Doors**
- **Walls, Floors, Ceilings & Finishes**
- **Conveying**
- **Plumbing**
- **HVAC**
- **Electrical**

Suggested Frequency of Inspection

- **Roof, Plaza & Below Grade Waterproofing**
 - Biannual
 - Fall Before Winter
 - Spring After Winter
 - After Storm
 - After Work on Roof
- **Façade & Structural Systems**
 - Self Inspection: Annual
 - Professional Inspection: Every 5 Years
- **Other Systems**
 - Annual Organized Self Inspection

Life Expectancy – Dependent on Install & Exposure

- **Building – 50 Years**
- **Roofing**
 - Metal – 25 Years
 - BUR & SBS Mod-Bit – 17 Years
 - APP Mod-Bit, EPDM, PVC – 14 Years
 - TPO – 13 Years
 - Polyurethane Foam – 12 Years
- **Sealants – 10 to 20 Years**
 - Silicone
 - Polyurethane
- **Traffic Bearing Membrane:**
 - 5 to 20 years
- **Below Grade Waterproofing:**
 - 50 Years (Modern)
- **Protected Waterproof Membrane:**
 - 50 Years (Modern)

Learning Objectives

- **Building Structure Inspection**
 - Champlain Towers Collapse
 - Structural Engineering 101
 - Failure Mechanisms
 - Concrete, Masonry, Steel, & Wood
 - Laws & Standards

Questions?

Scott L. Weiland PE SE
sweiland@ieiusa.com
678-570-7399 (c)



Atlanta Office

Innovative Engineering Inc.
3380 Trickum Road, Bldg. 500, Suite 100
Woodstock, Georgia 30188
678-883-5868 (direct)

Seattle Office

Innovative Engineering Inc.
11335 NE 122nd Way, Suite 105
Kirkland, Washington 98034
206-279-4360, X-202